LIEBL Remodel Addition

Case Study Presentation 03/04/2025

In an effort to support the design direction of the renovation at 226 Sopris Ave, and reflect the design intent of the Guidelines for Historic Buildings, we are providing this reference document. The images referenced are of local buildings, both historic and newer construction, as case studies for the project at 226 Sopris Ave.





pair of mulled windows at 1:1





single and mulled = windows at approx. 1:1.1







single window at 1:1

Liebl Remodel | SHM# 24-069 03/04/2025 4


Unknown Address



bank of windows at approx. 1.2: 1













windows at 1:1 p












1:1 windows



mulled 1:1 windows,





1:1 windows



